



FOR IMMEDIATE RELEASE: June 12, 2013  
CONTACT: Michael Young, PIO, 623-238-0179

## ELECTRICAL MALFUNCTION RESPONSIBLE FOR GLENDALE HOUSE FIRE

**Glendale, Ariz.** — Glendale Fire Investigators say a house fire at 5500 North 73<sup>rd</sup> Avenue on the morning of June 12 was caused by an electrical malfunction within the stove range hood. The fire traveled rapidly up the wall into the attic and caused the roof to collapse in the middle of the residence.

The single story residence was being used as a community placement home for Southwest Behavior Center. Four adults have been displaced because of the fire.

One firefighter was transported to the hospital after he started to experience heat exhaustion symptoms and has since been released.

The fire is being classified as accidental.

